



# VIBECHECK PRO

**Vibration Analysis- Laser Alignment- Balancing- Ultrasound- Oil Analysis**

**VibeCheck Pro, K30 Canary Mews,  
Arlington Estate, Harare, Zimbabwe**

**tel: +263771180034      website: [www.reliabilityintegritycentre.com](http://www.reliabilityintegritycentre.com)**

## **Vibration Analysis Survey Report**

**Client:**

**Fourways Crushing Plant**

**Contact:**

**Eng C Tekwani**

**Report No:**

**VCP003/01/0026**

**Survey Date:**

**21 January 2026**




## Vibration Analysis -Fault Priority Definitions

(As per ISO 10816)

Extreme	1	Immediate action is required. Consider shutting down the equipment and taking repair action now
Serious	2	Take maintenance action during the next planned downtime or maintenance period
Moderate	3	Issue is present but no immediate repair action is required. Continue to monitor
OK	4	No repair action is recommended. Continue to monitor and trend



## ALARM STATUS REPORT





## Summary Report

#	Equipment ID	Asset	Status	Fault
1	Jaw Crusher	Motor	P2	Structural looseness, Unbalance
2	Cone Crusher A	Motor	P4	Vibration Acceptable
3	Cone Crusher A	Crusher	P2	Bearing fault
4	Cone Crusher B	Motor	P2	Structural looseness
5	Cone Crusher B	Crusher	P1	Bearing fault, Lubrication fault
6	Vibro Screen 1	Motor	P1	Structural looseness, Belt Misalignment
7	Vibro Screen 2	Motor	P1	Structural looseness, Loose belts
8	Vibro Screen 3	Motor	P1	Structural looseness

## Detailed Reporting

### Fourways Crushing Plant/ Jaw Crusher - Motor

**Fault:** Structural looseness, Unbalance


P1  
Extreme

**Date:** 21 January 2026


**Findings:** Overall vibration on the motor NDE horizontal is trending upwards from 3.0 to **9.8** mm/s RMS. Spectra shows a dominant 1x vibration, which is characteristic to structural looseness. Motor DE bearing exhibits a strong 1x vibration suspected from the crusher running speed, this characteristic to unbalance.

**Recommendations:** Inspect and address any loose motor hold down bolts or weakened structures supporting the motor and the crusher. Inspect motor cooling fan and crusher pulleys for stuck dust accumulation and clean to remove dust accumulation.

### Motor NDE Horizontal



### Motor NDE Horizontal



## Fourways Crushing Plant/ Cone Crusher A - Crusher

**Fault:** Bearing fault


P2  
Serious

**Date:** 21 January 2026


**Findings:** Time waveform shows distinct impacting of up to **5.7 G's**, which can be associated with bearing fault. Suspected bearing defect at 225Hz.

**Recommendations:** Ensure the crusher bearings are adequately lubricated. Continue to monitor and trend.

### Crusher NDE Horizontal



### Crusher NDE Horizontal



## Fourways Crushing Plant/ Cone Crusher B - Motor

**Fault:** Structural looseness


P2  
Serious

**Date:** 21 January 2026


**Findings:** Overall vibration on the motor DE Horizontal is trending upwards from **11.5** to **5.8** mm/s RMS. Spectra shows 1x vibration which is characteristic to structural looseness.

**Recommendations:** Inspect and address any loose motor hold down bolts or weakened structures supporting the motor. The recommended practice is to isolate the motor and crusher structural framework.

### Motor DE Horizontal



### Motor DE Horizontal



## Fourways Crushing Plant/ Cone Crusher B - Crusher

**Fault:** Bearing fault, Lubrication fault


P1  
Extreme

**Date:** 21 January 2026


**Findings:** Overall vibration on the crusher NDE Horizontal is trending upwards from **9.2** to **16.4** mm/s RMS. Time waveform plot shows distinct impacting of up to **14.8 G's**, which can be associated with bearing fault. Random broadband noise floors dominate the spectrum which is associated with lubrication fault.

**Recommendations:** Ensure the crusher bearings are adequately lubricated. Continue to monitor and trend.

### Crusher NDE Horizontal



### Crusher NDE Horizontal



## Fourways Crushing Plant/ Vibro Screen 1 - Motor

**Fault:** Structural looseness, Belt Misalignment

**Date:** 21 January 2026



**P1  
Extreme**

**Findings:** Overall vibration on the motor DE vertical is trending upwards at **50.9 mm/s RMS**.



Spectra shows a strong 1x vibration which is characteristic to structural looseness. Axial vibration is upwards from **13.3** to **21.8 mm/s RMS**, this is an indication of belt misalignment

**Recommendations:** Address any loose motor hold down bolts, weakened structures to improve the structural rigidity. Inspect belts for wear and damage and replace as per condition, schedule for belt alignment. Visible cracked framework supporting the motor.

### Motor DE Vertical



### Motor DE Axial



## Fourways Crushing Plant/ Vibro Screen 2 - Motor

**Fault:** Structural looseness, Loose belts


P1  
Extreme

**Date:** 21 January 2026


**Findings:** Overall vibration on the motor NDE Horizontal is trending at **57.8** mm/s RMS. Spectra shows a strong 1x vibration which is characteristic to structural looseness. Drive belts were flapping indication unequal belt tensioning.

**Recommendations:** Inspect and address any loose motor hold down bolts, weakened structures to improve the structural rigidity. Replace the belts and ensure all belts are equally tensioned. Inspect motor cooling fan for dust accumulation and clean as per condition of the fan. Visible cracked framework supporting the motor

### Motor NDE Horizontal



### Motor NDE Horizontal



## Fourways Crushing Plant/ Vibro Screen 3 - Motor

**Fault:** Structural looseness


P1  
Extreme

**Date:** 21 January 2026


**Findings:** Overall vibration on the motor NDE Horizontal is trending at **7.6 mm/s RMS**. Spectra shows a strong 1x vibration which is characteristic to structural looseness.

**Recommendations:** Inspect and address any loose motor hold down bolts, weakened structures to improve the structural rigidity. Inspect motor cooling fan for dust accumulation and clean as per condition of the fan.

### Motor NDE Horizontal



### Motor NDE Horizontal





## Observations

1. Structures supporting the electrical motors on the screens, in particular screen 1 and 2, are damaged resulting in excessive vibrations.
2. All the drives are running with inadequate belts and misaligned.
3. Plan to reinforce the motor supporting structures to improve rigidity.
4. Plan to isolate motor base-frames from the crusher to minimise transmitted vibrations.