



Work Order WO-263
Tenant: Fourways Group
Asset: 44 - CONES x2 Motor
PRIORITY: HIGH

Status open
Priority high
Type corrective
Due 2026-02-03
Approval -
Created 2026-01-27 20:21:26
Originator Cleopas Tekwani
Assigned To Benjamin Kambasha

Description

Vibration analysis report VCP003/01/0026 (2026-01-21) flagged Structural looseness for CONES x2 Motor.
Findings: Motor DE horizontal vibration shows 1x vibration typical of structural looseness.

Remedial Action Plan

#	Action
1	Inspect and torque motor hold-down bolts; repair or reinforce motor support structure.
2	Isolate motor base-frame from crusher structure using isolation pads/shims to reduce transmitted vibration.
3	Verify alignment and re-test vibration after isolation.

Parts & Resources

SKU	Description	Qty	Unit Cost	Total Cost
-	No parts recorded.	-	-	-

Notes & Updates

Time	Type	By	Note
-	-	-	No notes yet.