



Work Order WO-264
Tenant: Fourways Group
Asset: 5 - Cone Crusher 2
PRIORITY: CRITICAL

Status open
Priority critical
Type corrective
Due 2026-01-28
Approval -
Created 2026-01-27 20:21:26
Originator Cleopas Tekwani
Assigned To Benjamin Kambasha

Description

Vibration analysis report VCP003/01/0026 (2026-01-21) flagged Bearing fault, lubrication fault for Cone Crusher 2.
Findings: Crusher NDE vibration trending upwards; impacting up to 14.8 Gs with broadband noise indicating lubrication fault.

Remedial Action Plan

#	Action
1	Lubricate bearings and verify lubricant flow/quality; flush or replace contaminated lubricant.
2	Inspect bearings for damage/clearance and schedule replacement if impacts persist.
3	Check seals and lubrication points; repair leaks and ensure correct grease/oil delivery.
4	Re-test vibration after lubrication and corrective work.

Parts & Resources

SKU	Description	Qty	Unit Cost	Total Cost
-	No parts recorded.	-	-	-

Notes & Updates

Time	Type	By	Note
-	-	-	No notes yet.